



Overview: Part of spill impact on 4" Agbada 2 Well2 Gaslift Flowline Right of Way at Omuohia. Picture was taken during Joint Investigation of 19th October 2014.



Close-up: Failed weld on 4" Agbada 2 Well2 Gaslift Flowline at Omuohia. Picture was taken during Joint Investigation of 19th October 2014.