



Overview: Part of spill impact from Imo River Well 59T Flowline at Igirukwu. Picture was taken during Joint Investigation of 25th February 2015.



Close-up: Illegal fitting on Imo River Well 59T Flowline at Igirukwu. Picture was taken during Joint Investigation of 25th February 2015.