



Overview: Part of spill impact on 8" Afam Well27 Flowline Right of Way at Egberu. Picture was taken during Joint Investigation of 4th July 2015.



Close-up: Position of drilled hole pointed out by JIT member with stick on 8" Afam Well2 Flowline at Egberu. Hazing effecting picture clarity is due to gas leaking from drill hole.