




Overview: Part of superficial impact (spray) on vegetation on Nkali Well 10L Flowline at Odagwa. Picture was taken during Joint Investigation of 26th July 2015.



Close-up: Hole created by gas release and Failed clamp on Nkali Well 10L Flowline at Odagwa. Picture was taken during Joint Investigation of 26th July 2015.