



Overview: Part of spill impact on Adibawa Well8SL Right of Way at Edagberi. Picture was taken during Joint Investigation of 13th July 2015.



Close-up: Tampered Flange on Adibawa Well8SL Right of Way at Edagberi. Picture was taken during Joint Investigation of 13th July 2015.



Close-up: Loosened bolts on Adibawa Well8SL at Edagberi. Picture was taken during Joint Investigation of 18th February 2016.