




Overview: Part of spill impact on Adibawa Well10S Flowline Right of Way at Edagberi/Betterland. Picture was taken during Joint Investigation of 19th of March 2015.



Close-up: Failed clamp on Adibawa Well10S Flowline at Edagberi/Betterland. Picture was taken during Joint Investigation of 19th of March 2015.