



**Overview:** Part of spill impact on Imo River Well 33L Flowline Right of Way at Ipu West. Picture was taken during Joint Investigation of 30<sup>th</sup> October 2015.



**Close-up:** Illegal fitting on Imo River Well 33L Flowline at Ipu West. Picture was taken during Joint Investigation of 30<sup>th</sup> October 2015.