



Overview: Part of spill impact on Obigbo North Well28L Wellhead Right of Way at Imeh. Picture was taken during Joint Investigation of 14th September 2015.



Close-up: Initial position of missing Christmas Tree Casing Head valves on Obigbo North Well28L Wellhead at Imeh. Picture was taken during Joint Investigation of 14th September 2015.