




**Overview:** Part of spill impact on Obigbo South Well3L Wellhead Slot at Umusia. Picture was taken during Joint Investigation of 14<sup>th</sup> September 2015.



**Close-up:** Leak due to corrosion on Kerotex Needle valve at Obigbo South Well3L Wellhead at Umusia. Picture was taken during Joint Investigation of 14<sup>th</sup> September 2015.