



Overview: Part of spill impact on 20" Otumara-Escravos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 1<sup>st</sup> November 2016.



Close-up: Oily Water bubbling out from Illegal Fitting on 20" Otumara-Escravos Pipeline at Ugboegungun. Picture was taken during Joint Investigation of 1<sup>st</sup> November 2016.