



Overview: Containment boom and oil slick observed around the leak point on 48" Forcados Terminal Export Line. Picture was taken during Joint Investigation of 17th February 2016.



Overview: Part of spill impact from 48" Forcados Terminal Export Line. Picture was taken during Joint Investigation of 18th February 2016.



Overview: Part of spill impact from 48" Forcados terminal Export Line. Picture was taken during Joint Investigation of 20th February 2016.



Overview: Part of spill impact from 48" Forcados terminal Export Line. Picture was taken during Joint Investigation of 20th February 2016.