



**Overview:** Part of spill impact on Ubie Well5LS Flowline Right of Way at Idu Ekpeye. Picture was taken during Joint Investigation of 29<sup>th</sup> January 2016.



**Close-up:** Hacksaw cut (Point 1) on Ubie Well5LS Flowline at Idu Ekpeye. Picture was taken during Joint Investigation of 29<sup>th</sup> January 2016.



Close-up: Hacksaw cut (Point 2) on Ubie Well5LS Flowline at Idu Ekpeye. Picture was taken during Joint Investigation of 29<sup>th</sup> January 2016.