



Overview: Part of spill impact on Obigbo North Well 26T_18S_20T_three disused Flowlines at Umuwalia. Picture was taken during Joint Investigation of 21st July 2016.



Close-up: Irregular holes and Marks on Obigbo North Well 26T_18S Flowlines at Umuwalia. Picture was taken during Joint Investigation of 21st July 2016.