


Overview: Part of Spill Impact on Agbada2 Well 41/42/43 Cluster Right of Way at Omuohia/Omuokoji. Picture was taken during Joint Investigation of 20<sup>th</sup> May 2016.



Close-up: Cathodic Leak joint damaged by fire on Agbada2 Well 41/42/43 Cluster at Omuohia/Omuokoji. Picture was taken during Joint Investigation of 20<sup>th</sup> May 2016.



Close-up: Damaged Flowline on Agbada2 Well 41/42/43 Cluster at Omuohia/Omuokoji.  
Picture was taken during Joint Investigation of 20<sup>th</sup> May 2016.