



Overview: Part of spill impact on Bonny Terminal tank15-10'' drainline flange at Bonny. Picture was taken during Joint Investigation of 1st December 2016.



Close-up: Leaking flange on Bonny Terminal tank15-10'' drainline flange at Bonny. Picture was taken during Joint Investigation of 1st December 2016.