



Overview: Part of spill impact on Etelebou Well-11T Well head at Akenfa. Picture was taken during Joint Investigation of 2nd December 2016.



Close-up: Tampered Cork valve on Etelebou Well-11T Well head at Akenfa. Picture was taken during Joint Investigation of 2nd December 2016.