




Overview: Part of spill impact on Kanbo Wells - 7L/S and 9T Wellheads Cluster at Agbidiana. Picture was taken during Joint Investigation of 27th October 2016.



Close-up: Position of stolen CCU actuator on Kanbo Wells - 7L/S and 9T Wellheads Cluster at Agbidiana. Picture was taken during Joint Investigation of 27th October 2016.



Close-up: Position of stolen CCU actuator on Kanbo Wells - 7L/S and 9T Wellheads Cluster at Agbidiana. Picture was taken during Joint Investigation of 27th October 2016.



Close-up: Tampered CCU actuator on Kanbo Wells - 7L/S and 9T Wellheads Cluster at Agbidiana. Picture was taken during Joint Investigation of 27th October 2016.