



Overview: Part of spill impact on 6" Kanbo Well 6T Flowline at Agbidiama. Picture was taken during Joint Investigation of 27<sup>th</sup> October 2016.



Close-up: Hacksaw cut on 6" Kanbo Well 6T Flowline at Agbidiama. Picture was taken during Joint Investigation of 27<sup>th</sup> October 2016.



Overview: Hacksaw cut on 6" Kanbo Well 6T Flowline at Agbidiana. Picture was taken during Joint Investigation of 27<sup>th</sup> October 2016.