


Overview: Part of spill impact on Imo River 1 Well 5S Flowline Right of Way at Igiriukwu. Picture was taken during Joint Investigation of 4th Aug 2017.



Close-up: Hacksaw Cut on Imo River 1 Well 5S Flowline at Igiriukwu. Picture was taken during Joint Investigation of 4th Aug 2017.