

JOINT INVESTIGATION REPORT

INCIDENT NO: 1986368 JIV report S/N: 0954

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Spill incident Number: 1986368 2. Type of incident* OIL SPILL/FIRE
3. Name of Location 20" Rumuekpe - Nkpoku Trans Niger Pipeline
4. Name of nearest community IBAA 5. State: RIVERS 6. LGA EMOTUA
7. Type of Production facility/Installation OIL PIPELINE
8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LTD

B. INCIDENT INFORMATION:

9. Details of incident

- a. Date of incident: 15TH DECEMBER 2017
b. Start date/time of investigation: 22ND DECEMBER 2017 AND 29TH DECEMBER 2017
c. Investigation End date: 30TH DEC, 2017 Actual investigation duration, days: THREE DAYS
d. Description of spill point environment

- | | | |
|---|-------------------------------------|---|
| <input type="checkbox"/> Firm soil | <input type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water | <input type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe surface |
| <input type="checkbox"/> Well Platform (on Water) | <input type="checkbox"/> Drill Rig | |

Additional observations around the spill point: ON THE SECOND VISIT TO INCIDENT SITE, THE JOINT INVESTIGATION TEAM ON ARRIVAL OBSERVED THE INCIDENT SITE HAS BEEN SET ON FIRE BY UNKNOWN PERSON(S)

e. Description of leak point (tick as applicable);

- | | | |
|---|--|--|
| <input checked="" type="checkbox"/> Drilled hole | <input type="checkbox"/> Hack saw cut | <input type="checkbox"/> Tear (_____) |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Corrosion | <input type="checkbox"/> Others(specify) _____ | |

f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3rd party damage
 Operational Mystery spills Others(specify) _____

*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire.

JOINT INVESTIGATION REPORT

INCIDENT NO: 1986368 JIV report S/N: 0954

g. Spill point coordinates

h. Measuring unit

WGS 84

Northing: (LATITUDE)	Easting: (LONGITUDE)
4.85368	6.83262

C. RISK ASSESSMENT

10. Type of environment:

- Land
 Swamp
 Water
 Seasonal swamp
 Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land
 Swamp
 Water
 River (identify) _____

ii. Weather condition

- Rain
 Sunny
 Dry
 Wet
 Windy
 Hot
 cool

11. Distance from the nearest sensitive habitat

- | | |
|--|-----------|
| <input type="checkbox"/> Government reserved and designated protected area | [NIL ,m] |
| <input type="checkbox"/> Drinking water source | [NIL ,m] |
| <input type="checkbox"/> Built up area | [NIL ,m] |
| <input type="checkbox"/> Farmlands | [5 ,m] |
| <input type="checkbox"/> Fish Farm/pond | [NIL ,m] |
| <input type="checkbox"/> Fishing net | [NIL ,m] |
| <input type="checkbox"/> Others (specify). | |

12. Containment measures put in place;

- Booms
 Trench
 Dyke
 Natural depression
 Pit
 None
- Others: _____

13. Any pictures or video coverage? [Y] [N]

14. Further response/repair initiated as at the time of JIV? [Y] [N]

if yes to item 14. give brief description:

REPAIR WORK BY CLAMPING COMPLETED

15. Was there any disruption to the investigation? [Y] [N]

JOINT INVESTIGATION REPORT

INCIDENT NO: 1986368 JIV report S/N: 0954

If yes to item 15 give brief description:

NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	NONE WITHIN AREA OF IMPACT				

17. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	NONE WITHIN AREA OF IMPACT					


18. Fishing Nets/Fish Ponds

S/N	Nets/Ponds	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

19. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

E. GRAPHIC DESCRIPTION OF LEAK POINT (While detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix I) :- **SECTIONAL VIEW OF 20" Rumuŋkpe - Nkpoku TRANS NIGERI PIPELINE AT IBAA, SHOWING:- LEAK DUE TO 10mm DRILLED HOLE AT 3'O' CLOCK POSITION.**



PT_ID	LAT_Y	LONG_X
SP	4.95368	6.83262
1	4.95401	6.83311
2	4.95407	6.83316
3	4.95412	6.83314
4	4.95412	6.83309
5	4.95407	6.83308
6	4.95401	6.83305
7	4.95402	6.833
8	4.95398	6.83297
9	4.95398	6.83292
10	4.9539	6.8329
11	4.95388	6.83285
12	4.95383	6.83283
13	4.9538	6.83274
964	4.9538	6.83257
965	4.95371	6.8326
972	4.95366	6.83253
973	4.95357	6.83253
974	4.95348	6.83259
975	4.95347	6.83272
976	4.95349	6.83273
977	4.9535	6.8327
978	4.95355	6.83274
979	4.95363	6.83277
980	4.95363	6.8328
981	4.95366	6.83281
982	4.95356	6.83288
983	4.95345	6.83301
984	4.95344	6.83327
985	4.95347	6.8334
986	4.95353	6.83339
987	4.95355	6.83329
988	4.95358	6.83326
989	4.95367	6.83329
990	4.9537	6.83332
991	4.9537	6.83336
992	4.95375	6.83329
993	4.9538	6.83326
994	4.95383	6.83329
995	4.9539	6.83334
996	4.9539	6.83337
997	4.954	6.83333
998	4.95403	6.83329
999	4.95398	6.83317
996	4.95372	6.83332
997	4.95372	6.83334
998	4.9537	6.83334
969	4.95372	6.83336
970	4.95372	6.83338

PT_ID	LAT_Y	LONG_X
971	4.9537	6.83338

JOINT INVESTIGATION REPORT

INCIDENT NO: 1986368 JIV report S/N: 0954

G. INCIDENT INFORMATION:

a. Impacted Area Details

- Total calculated area of impact 0.40HA
- Impact within R.O.W YES
- Impact outside R.O.W YES

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} :	NIL	Barrels
---------------------------	-----	---------

Controlled recovery/evacuation from source with no impact to environment:

NIL	Barrels
-----	---------

c. Net Estimated Spilled Volume V_{Est} (bbls)* =

58.25 BARRELS

Estimated Reported Volume V_{rep} (bbls) =**

59 BARRELS

***Notes:**

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

NOT APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site: Conversion of m³ to barrels is Volume: (m³) x 6.29: **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number:
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl
 Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl
 Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl

Wherever this estimation tool is not applicable please refer to paragraph 6e (Deviations) of the JIV procedure to use appropriate steps for volume estimation: record the calculation in a plain sheet of paper and attach to the JIV report.

JOINT INVESTIGATION REPORT

INCIDENT NO: 1986368 JIV report S/N: 0954

d. General Status of the site

- i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
- ii. Investigation of the incident site showed that there is residual impact on site requiring further works

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Asset Owner:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT

INCIDENT NO: 1986368 JIV report S/N: 0954

f. Appendix 1: Overview sketch of the site

