




**Overview:** Part of spill impact on Imo River 1 Well 36 Flowline IgiriUkwu-Owaza. Picture was taken during Joint Investigation of 15<sup>th</sup> February 2017.



**Close-up:** Hacksaw cut on Imo River 1 Well 36 Flowline IgiriUkwu-Owaza. Picture was taken during Joint Investigation of 15<sup>th</sup> February 2017.