



Overview: Part of spill impact on 4" Adibawa Well 2S Flowline Right of Way at Edagberi-Betterland. Picture was taken during Joint Investigation of 5<sup>th</sup> July 2017.



Close-up: Section of Missing Flowline on 4" Adibawa Well 2S Flowline at Edagberi-Betterland. Picture was taken during Joint Investigation of 5<sup>th</sup> July 2017.



Close-up: Hacksaw Cut on 4" Adibawa Well 2L Flowline at Edagberi-Betterland. Picture was taken during Joint Investigation of 5<sup>th</sup> July 2017.