



Overview: Part of spill impact on 4" Tunu Well-4L Flowline at Agbidiana. Picture was taken during Joint Investigation of 28<sup>th</sup> July 2017.



Close-up: Corrosion on 4" Tunu Well-4L Flowline at Agbidiana. Picture was taken during Joint Investigation of 28<sup>th</sup> July 2017.