



Overview: Part of spill impact on 4" Adibawa Well 23 Disused Flowline at Edagberi Better Land. Picture was taken during Joint Investigation of 27th October 2017.



Close-up: Missing Flowline on 4" Adibawa Well 23 Disused Flowline at Edagberi Better Land. Picture was taken during Joint Investigation of 27th October 2017.