




**Overview:** Part of spill impact Ubie Well 5 L/S Well head at Idu-Ekpeye. Picture was taken during Joint Investigation of 12<sup>th</sup> June 2018.



**Close-up:** Tampered Master Valve bolts on Ubie Well 5 L/S Well head at Idu-Ekpeye. Picture was taken during Joint Investigation of 12<sup>th</sup> June 2018.