




Overview: Part of spill impact on Imo River Well 36 Gas Lift Line Igiriukwu-Owaza. Picture was taken during Joint Investigation of 21st November 2018..



Close-up: Leaking Hacksaw Cut on Imo River Well 36 Gas Lift Line Igiriukwu-Owaza. Picture was taken during Joint Investigation of 21st November 2018.