

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2213884 JIV report S/N: 0183

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

## A. GENERAL INFORMATION:

1. Spill incident Number: 2213884 2. Type of incident\* OIL SPILL  
3. Name of Location 24" BOMU - BONNY TRANS NIGER PIPELINE  
4. Name of nearest community OKIOKIRI 5. State: RIVERS 6. LGA ANDONI  
7. Type of Production facility/Installation OIL PIPELINE

8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED PIPELINE

## B. INCIDENT INFORMATION:

### 9. Details of incident

- a. Date of incident: 26<sup>th</sup> NOVEMBER, 2018  
b. Start date/time of investigation: 28<sup>th</sup> NOVEMBER, 2018  
c. Investigation End date: 28<sup>th</sup> NOVEMBER, 2018 Actual investigation duration, days: ONE DAY  
d. Description of spill point environment

- |   |  |   |
|---|--|---|
| <input type="checkbox"/> Firm soil                | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input checked="" type="checkbox"/> Swampy     | <input type="checkbox"/> Exposed pipe surface               |
| <input type="checkbox"/> Well Platform (on Water) | <input type="checkbox"/> Drill Rig             |   |

Additional observations around the spill point:

NOT APPLICABLE

### c. Description of leak point (tick as applicable);

- |   |  |  |
|---|--|--|
| <input type="checkbox"/> Drilled hole   | <input type="checkbox"/> Hack saw cut          | <input type="checkbox"/> Tear (_____)                                      |
| <input type="checkbox"/> Complete Rupture                                     | <input type="checkbox"/> Inward dent           | <input type="checkbox"/> Well head tampering                               |
| <input checked="" type="checkbox"/> Failed Weld-on illegal hot tap valve      | <input type="checkbox"/> Failed Clamp          | <input type="checkbox"/> Missing Pipeline/Flowline                         |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point | <input type="checkbox"/> Saver-pit over flow   | <input type="checkbox"/> Third party tampering with Clamp                  |
| <input type="checkbox"/> Third party tampering with valve setting             | <input type="checkbox"/> Bulging Outward       | <input type="checkbox"/> Third party tampering with flange                 |
| <input type="checkbox"/> Flare System/Burid wall failure                      | <input type="checkbox"/> Cold vent             | <input type="checkbox"/> Surge vessel overflow                             |
| <input type="checkbox"/> Valve Failure  | <input type="checkbox"/> Relief valve failure  | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Corrosion  | <input type="checkbox"/> Others(specify) _____ |  |

### f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Mystery spills  Others(specify) \_\_\_\_\_

\*This can be: a) Oil-Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire. Version 2018/01  
Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).



# JOINT INVESTIGATION REPORT

INCIDENT NO: 22/3884 JIV report S/N: 0183

If yes to item 15 give brief description:

NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

**16. Structures / Properties**

| S/N                        | Type of Structures | Description | Size | Number | Comments |
|----------------------------|--------------------|-------------|------|--------|----------|
| NONE WITHIN AREA OF IMPACT |                    |             |      |        |          |

**17. Crops/Economic Trees**

| S/N                        | Type of crops | Young | Medium | Matured | Quantity | Comments |
|----------------------------|---------------|-------|--------|---------|----------|----------|
| NONE WITHIN AREA OF IMPACT |               |       |        |         |          |          |

**18. Fishing Nets/Fish Ponds**


| S/N                        | Nets/Ponds | Description | Quantity/Size | Comments |
|----------------------------|------------|-------------|---------------|----------|
| NONE WITHIN AREA OF IMPACT |            |             |               |          |

**19. Others (Specify) i.e. Animal Traps**

| S/N                        | Others | Description | Quantity/Size | Comments |
|----------------------------|--------|-------------|---------------|----------|
| NONE WITHIN AREA OF IMPACT |        |             |               |          |

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detailed report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTIONAL VIEW OF 24" BOMU - BONNY TRANS NIGER PIPELINE AT OKOKIRI SHOWING: - FAILED 6" WELD-ON ILLEGAL HOT TAP VALVE INSTALLED AT 12 O' CLOCK POSITION BY UNKNOWN PERSON(S)





# JOINT INVESTIGATION REPORT

INCIDENT NO: 2213884 JIV report S/N: 0183

## G. INCIDENT INFORMATION:

### a. Impacted Area Details:

- Total calculated area of impact 0.03074 Ha
- Impact within R.O.W YES
- Impact outside R.O.W NO

### b. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):

|                            |            |         |
|----------------------------|------------|---------|
| Recovered oil: $V_{rec}$ : | <u>NIL</u> | Barrels |
|----------------------------|------------|---------|

Controlled recovery/evacuation from source with no impact to environment:

|            |         |
|------------|---------|
| <u>NIL</u> | Barrels |
|------------|---------|

|   |
|---|
| c. <u>Net Estimated Spilled Volume <math>V_{est}</math> (bbls)** =</u><br><u>2.36 BARRELS</u> |
| <u>Estimated Reported Volume** <math>V_{rep}</math> (bbls) =</u><br><u>3 BARRELS</u>          |

#### \*Notes:

- Volume estimation was done using an excel based tool (see attached for details on the calculation).
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled volume in the box below:

NOT APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is Volume ( $m^3$ ) x 6.29; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl  
Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl  
Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for volume estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2018/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2213884 JIV report S/N: 0183

## d. General Status of the site

- |  |
|--|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>  |

## c. Representatives

|   |
|---|
| <p>This report was filled, agreed and signed by the following joint investigation team representatives:</p> <ul style="list-style-type: none"><li>• Host Community: <input checked="" type="checkbox"/></li><li>• Department of Petroleum Resources [DPR]: <input checked="" type="checkbox"/></li><li>• National Oil Spill Detection and Response Agency [NOSDRA]: <input checked="" type="checkbox"/></li><li>• State Ministry of Environment [SME]: <input checked="" type="checkbox"/></li><li>• Asset Owner: <input checked="" type="checkbox"/></li><li>• Signatories agree with reported findings: <input checked="" type="checkbox"/></li><li>• Separate DPR form has been filled out with same findings <input type="checkbox"/></li></ul> <p style="text-align: right;"><i>Tick as applicable</i></p> |
|---|

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2213884 JIV report S/N: 0283

f. Appendix 1: Overview sketch of the site

