




Overview: Part of spill impact on Imo River Well 59T Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 15th September 2018.



Close-up: Illegal fitting on Imo River Well 59T Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 15th September 2018.