



Overview: Part of spill impact on Imo River–Well 31L Flowline at Odagwa-Umuadeokwara.
Picture was taken during Joint Investigation of 6th September 2018.



Close up: Illegal fitting on Imo River2 – Well 31L Flowline at Odagwa-Umuadeokwara .
Picture was taken during Joint Investigation of 6th September 2018.