




Overview: Part of spill impact on 4" Imo River2 Well 21L Flowline at Odagwa. Picture was taken during Joint Investigation of 17th April 2019.



Close-up: Illegal Fitting on 4" Imo River2 Well 21L Flowline at Odagwa. Picture was taken during Joint Investigation of 17th April 2019