


**Overview:** Part of spill impact on on Imo River Well 25S Flowline at Odagwa. Picture was taken during Joint Investigation of 30<sup>th</sup> December 2019.



**Close-up:** Hack Saw Cut at 1 o'clock position on Imo River Well 25S Flowline at Odagwa. Picture was taken during Joint Investigation of 30<sup>th</sup> December 2019.