



Overview: Part of spill impact on Imo River Well 63T Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 31st July 2019.



Close-up: Corrosion on Imo River Well 63T Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 1st August 2019.