

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2342673 JIV report S/N: 0131

*(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)*

**A. GENERAL INFORMATION:**

- 1. Spill incident Number: 2342673      2. Type of incident\*: OIL SPILL
- 3. Name of Location 4<sup>th</sup> OPUKUSHI WELL 9T FLOWLINE
- 4. Name of nearest community EGBEMO-ANLAGIKI      5. State: BAYELSA 6. LGA EKEREMOR
- 7. Type of Production facility/Installation OIL FLOWLINE
- 8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

**B. INCIDENT INFORMATION:**

- 9. Details of incident
  - a. Date of incident: 6<sup>th</sup> MAY 2019
  - b. Start date/time of investigation: 7<sup>th</sup> MAY 2019 / 12 litres
  - c. Investigation End-date: 7<sup>th</sup> MAY 2019      Actual investigation duration, days: ONE (1) DAY
  - d. Description of spill point environment

- |   |                                      |   |
|---|--------------------------------------|---|
| <input type="checkbox"/> Firm soil                | <input type="checkbox"/> Loose soil. | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input type="checkbox"/> Swampy      | <input checked="" type="checkbox"/> Exposed pipe surface    |
| <input type="checkbox"/> Well Platform (on Water) | <input type="checkbox"/> Drill Rig   |   |

Additional observations around the spill point:

NOT APPLICABLE

**e. Description of leak point (tick as applicable);**

- |  |  |  |
|--|--|--|
| <input type="checkbox"/> Drilled hole                              | <input type="checkbox"/> Hack saw cut          | <input type="checkbox"/> Tear (_____)                                      |
| <input type="checkbox"/> Complete Rupture                          | <input type="checkbox"/> Inward dent           | <input type="checkbox"/> Well head tampering                               |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve      | <input type="checkbox"/> Failed Clamp          | <input checked="" type="checkbox"/> Missing Pipeline/Flowline              |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point | <input type="checkbox"/> Saver-pit over flow   | <input type="checkbox"/> Third party tampering with Clamp                  |
| <input type="checkbox"/> Third party tampering with valve setting  | <input type="checkbox"/> Bulging Outward       | <input type="checkbox"/> Third party tampering with flange                 |
| <input type="checkbox"/> Flare System/Bund wall failure            | <input type="checkbox"/> Cold vent             | <input type="checkbox"/> Surge vessel overflow                             |
| <input type="checkbox"/> Valve Failure                             | <input type="checkbox"/> Relief valve failure  | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Corrosion                                 | <input type="checkbox"/> Others(specify) _____ |  |

**f. Incident caused by:**

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage  Operational       Mystery spills       Others(specify) \_\_\_\_\_

\*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire.      Version 2018/01  
Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2342673 JIV report S/N: 0131

g. Spill point coordinates

Measuring unit

WGS 84

Northing: <u>LAST</u>	Easting: <u>LONG</u>
<u>4.91392</u>	<u>5.76271</u>

## C. RISK ASSESSMENT

10. Type of environment:

- Land    
  Swamp    
  Water    
  Seasonal swamp    
  Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land    
  Swamp    
  Water    
  River (identify) \_\_\_\_\_

ii. Weather condition

- Rain    
  Sunny    
  Dry    
  Wet    
  Windy    
  Hot    
  Cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area
- Drinking water source
- Built up area
- Farmlands
- Fish Farm/Pond
- Fishing net
- Others (specify): \_\_\_\_\_

[ ] ,m] } NONE WITHIN  
 [ ] ,m] } VICINITY  
 [ ] ,m] }  
 [ ] ,m] }  
 [ ] ,m] }  
 [ ] ,m] }

12. Containment measures put in place;

- Booms    
  Trench    
  Dyke    
  Natural depression    
  Pit    
  None
- Others: \_\_\_\_\_

13. Any pictures or video coverage?

[  ] [ N ]

14. Further response/repair initiated as at the time of JIV?

[ Y ] [  ]

If yes to item 14, give brief description:

---

15. Was there any disruption to the investigation?

[ Y ] [  ]

Version 2018/01

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2342673 JIV report S/N: 0131

If yes to item 15 give brief description:

NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

**16. Structures / Properties**

S/N	Type of Structures	Description	Size	Number	Comments
NONE WITHIN AREA OF IMPACT					

**17. Crops/Economic Trees**

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
NONE WITHIN AREA OF IMPACT						


**18. Fishing Nets/Fish Ponds**

S/N	Nets/Ponds	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

**19. Others (Specify) i.e. Animal Traps**

S/N	Others	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detailed report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1) A SECTION OF 4" OPUKUSHI WELL 9T FRONTLINE AT AGBIDIAMA SHOWING MISSING FLOWLINE (THEFT) BY UNKNOWN PERSONS



From WELL 9T TO OPUKUSHI FLOWSTATION

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2342673 JIV report S/N: 0131

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

20. Impacted-area boundary Coordinates *(If more, Print and attach as an appendix)*

WGS 84

S/N	Northing	LATITUDE	Easting	LONGITUDE
		4.9134		5.76238
		4.9134		5.76237
		4.91367		5.76235
		4.91368		5.76234
		4.91391		5.76272
		4.91393		5.7627

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2342673 JIV report S/N: 0131

**G. INCIDENT INFORMATION:**

**a. Impacted Area Details**

- Total calculated area of impact 0.015 Ha
- Impact within R.O.W YES
- Impact outside R.O.W YES

**b. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):**

Recovered oil ( $V_{rec}$ )	NIL	Barrels
-----------------------------	-----	---------

Controlled recovery/evacuation from source with no impact to environment:

NIL	Barrels
-----	---------

c. Net Estimated Spilled Volume $V_{est}$ (bbls) = <u>0.41 BARRELS</u>
Estimated Reported Volume** $V_{rep}$ (bbls) = <u>0.5 BARRELS</u>

**\*Notes:**

- Volume estimation was done using an excel based tool (see attached for details on the calculation).
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled volume in the box below:

NOT APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is Volume ( $m^3$ ) x 6.29; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ——— Reported volume = 16 bbl  
 Calculated volume = 0.35 bbl ——— Reported volume = 0.4 bbl  
 Calculated volume = 0.01 bbl ——— Reported volume = 0.1 bbl

Wherever this estimation tool is not applicable please refer to paragraph 6c. (Deviations) of the JIV procedure to use appropriate steps for volume estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2018/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2342673 JIV report S/N: 0131

## d. General Status of the site

i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/>
ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>


## e. Representatives

<p>This report was filled, agreed and signed by the following joint investigation team representatives:</p> <ul style="list-style-type: none"><li>• Host Community: <input checked="" type="checkbox"/></li><li>• Department of Petroleum Resources [DPR]: <input checked="" type="checkbox"/></li><li>• National Oil Spill Detection and Response Agency [NOSDRA]: <input checked="" type="checkbox"/></li><li>• State Ministry of Environment [SME]: <input checked="" type="checkbox"/></li><li>• Asset Owner: <input checked="" type="checkbox"/></li><li>• Signatories agree with reported findings: <input checked="" type="checkbox"/></li><li>• Separate DPR form has been filled out with same findings <input checked="" type="checkbox"/></li></ul> <p style="text-align: right;"><i>Tick as applicable</i></p>
--

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2342 673 JIV report S/N: 0131

f. Appendix I: Overview sketch of the site



Version 2018/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).