

JOINT INVESTIGATION REPORT

INCIDENT NO: 2497225 JIV report S/N: 1030078

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Mountain Incident Number: 2497225 2. Type of incident: OIL SPILL
3. Name of Location: 20" TRANS - ESCRANOS PIPELINE
4. Name of nearest community: UGBOEGUNG State: DELTA Local Authority: IGBA WARRI SOUTH WEST
7. Type of Production facility/Installation: OIL PIPELINE
8. Asset owner/District: THE SHELL PETROLEUM DEVELOPMENT COMPANY / PIPELINE

B. INCIDENT INFORMATION:

9. Details of incident

- a. Date Reported: 1ST NOVEMBER, 2019
b. Start date/time of investigation: 4TH NOVEMBER, 2019, AT 16:22 HRS
c. Investigation End date: 4TH NOVEMBER, 2019 Actual investigation duration, days: ONE (1) DAY

d. Description of spill point environment

- | | | |
|---|--|--|
| <input type="checkbox"/> Firm soil | <input type="checkbox"/> Loose soil | <input type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water | <input checked="" type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe surface |
| <input type="checkbox"/> Well Platform (on Water) | <input type="checkbox"/> Drill Rig | |

Additional observations around the spill point:

NOT APPLICABLE

e. Description of leak point (tick as applicable);

- | | | |
|--|---|--|
| <input type="checkbox"/> Drilled hole | <input type="checkbox"/> Hack saw cut | <input type="checkbox"/> Tear (_____) |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Others (specify) _____ | | |

f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3rd party damage
 Operational Others (including Mystery spills) _____

*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Situation d) construction e) Encroachment f) Fire, g) non leaking Theft point removed
Version 2019/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

JOINT INVESTIGATION REPORT

INCIDENT NO: 2497225 JIV report S/N: 1030078

g. Spill point coordinates

h. Measuring unit WGS 84

Northing:	Easting:
5.64777	5.14596

C. RISK ASSESSMENT

10. Type of environment:

- Land
 Swamp
 Water
 Seasonal swamp
 Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land
 Swamp
 Water
 River (identify) _____

ii. Weather condition

- Rain
 Sunny
 Dry
 Wet
 Windy
 Hot
 Cool

11. Distance to Sensitive habitat within 100m radius

- | | | | |
|--|---|-----|-------------------------------------|
| <input type="checkbox"/> Government reserved and designated protected area | [| [m] | NONE WITHIN
THE VICINITY |
| <input type="checkbox"/> Drinking water source | [| [m] | |
| <input type="checkbox"/> Built up area | [| [m] | |
| <input type="checkbox"/> Farmlands | [| [m] | |
| <input type="checkbox"/> Fish Farm/Pond | [| [m] | |
| <input type="checkbox"/> Fishing net | [| [m] | |
| <input type="checkbox"/> Others (specify): | [| [m] | |

12. Containment measures put in place;

- Booms
 Trench
 Dyke
 Natural depression
 Pit
 None

Others: _____

13. Any pictures or video coverage? [Y] [N]

14. Further response/repair initiated as at the time of JIV? [Y] [N]

If yes to item 14, give brief description:

NOT APPLICABLE

15. Was there any disruption to the investigation? [Y] [N]

JOINT INVESTIGATION REPORT

INCIDENT NO: 2497225 JIV report S/N: 1030078

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? (Y) (N)

If yes to item 16 give brief description: NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	NONE WITHIN AREA OF IMPACT				

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	NONE WITHIN AREA OF IMPACT					

19. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

20. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

A SECTION OF 20" TRANS-ESCAUDS PIPELINE AT OGBOEGUNGUN SHOWING A FAILED WELD-ON 4" FLANGE INSTALLED AT 12 O'CLOCK POSITION BY UNKNOWN PERSON.



FROM OTUMARA - ESCRAUDS MANIFOLD

JOINT INVESTIGATION REPORT

INCIDENT NO: 2497225 JIV report S/N: 1030078

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

21. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

S/N	Northing	Easting
1	5.65205	1.4623
2	5.65050	5.14560
3	5.64895	5.14510
4	5.64688	5.14688
5	5.64680	5.14694
6	5.64532	5.14805
7	5.64526	5.14791
8	5.64674	5.14680
9	5.64682	5.14674
10	5.64776	5.14590
11	5.64902	5.14494
12	5.65055	5.14551
13	5.65212	5.14604
14		

JOINT INVESTIGATION REPORT

INCIDENT NO: 2497225, JIV report S/N: 1030073

G. INCIDENT INFORMATION:

a. Impacted Area Details

- Total calculated area of impact 1.420 HA
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W YES

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} : NIL Barrels

Controlled recovery/evacuation from source with no impact to environment:


NIL Barrels

c. Net Estimated Spilled Volume V_{net} (bbls)* =	<u>4.28 BARRELS</u>
Estimated Reported Volume** V_{rep} (bbls) =	<u>5 BARRELS</u>

*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:



Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m^3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl
Calculated volume = 0.33 bbl — Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for volume estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).

JOINT INVESTIGATION REPORT

INCIDENT NO: 2497-225 JIV report S/N: 1030070

d. General Status of the site

- i. Joint investigation of the incident site found that there is no residual impact after the initial response and it therefore recommend that the site be closed out
- ii. Investigation of the incident site showed that there is residual impact on site requiring further works

e. Representatives

This report was filled, agreed and signed by the following Joint Investigation team representatives


- Host Community:
- Department of Petroleum Resources (DPR):
- National Oil Spill Detection and Response Agency (NOSDRA):
- State Ministry of Environment (SME):
- Shell Petroleum Development Company (SPDC):
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT

INCIDENT NO: 2497225 JIV report S/N: 1030778

f. Appendix 1: Overview sketch of the site



Version 2019/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

Page 7 of 8