

JOINT INVESTIGATION REPORT

INCIDENT NO: 2500137 JIV report S/N: 1030167

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Fountain Incident Number: 2500137 2. Type of incident* OIL SPILL
3. Name of Location: 8" ISIRI-IMO GATE DELIVERY LINE
4. Name of nearest community UZUAKU 5. State: ABIA 6. LGA UKWA WEST
7. Type of Production facility/Installation OIL PIPE LINE
8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED (SPDC) / PIPELINE

B. INCIDENT INFORMATION:

9. Details of incident

- a. Date Reported: 8th NOVEMBER, 2019
b. Start date/time of investigation: 8th NOV, 2019 / 1430HRS
c. Investigation End date: 8th NOV, 2019 Actual investigation duration, days: ONE DAY
d. Description of spill point environment

- | | | |
|---|-------------------------------------|---|
| <input type="checkbox"/> Firm soil | <input type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water | <input type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe surface |
| <input type="checkbox"/> Well Platform (on Water) | <input type="checkbox"/> Drill Rig | |

Additional observations around the spill point:

e. Description of leak point (tick as applicable);

- | | | |
|---|---|--|
| <input checked="" type="checkbox"/> Drilled hole | <input type="checkbox"/> Hack saw cut | <input type="checkbox"/> Tear (_____) |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve. | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Others(specify) _____ | | |

f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3rd party damage
 Operational Others (including Mystery spills) _____

*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire, g) non leaking Theft point removal
Version 2019/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment) ; Blue (Host Community)

JOINT INVESTIGATION REPORT

INCIDENT NO: 2500137 JIV report S/N: 1030167

g. Spill point coordinates

h. Measuring unit

NGS 8.4

Northing:	Easting:
4.8882	7.18307

C. RISK ASSESSMENT

10. Type of environment:

- Land
 Swamp
 Water
 Seasonal swamp
 Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land
 Swamp
 Water
 River (identify) _____

ii. Weather condition:

- Rain
 Sunny
 Dry
 Wet
 Windy
 Hot
 Cool

11. Distance to Sensitive habitat within 100m radius.

- Government reserved and designated protected area
- Drinking water source
- Built up area
- Farmlands
- Fish Farm/Pond
- Fishing net
- Others (specify):

[,m] } NONE OBSERVED
 [,m] } WITHIN VICINITY
 [,m]
 [,m]
 [,m]
 [,m]

12. Containment measures put in place;

- Booms
 Trench
 Dyke
 Natural depression
 Pit
 None
 Others: _____

13. Any pictures or video coverage?

[Y] [N]

14. Further response/repair initiated as at the time of JIV?

[Y] [N]

If yes to item 14, give brief description:

CLAMPING ACTIVITY IN PROGRESS & EVACUATION
OF FREE PHASE CRUDE OIL

15. Was there any disruption to the investigation?

[Y] [N]

JOINT INVESTIGATION REPORT

INCIDENT NO: 2500137 JIV report S/N: 1030167

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y] [N]

If yes to item 16 give brief description: NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
NONE WITHIN AREA OF IMPACT					

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
NONE WITHIN AREA OF IMPACT						


19. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

20. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1) A SECTION OF 8" SIMIRI-IMO GATE MANIFOLD DELIVERY LINE AT UZUAKU SHOWING 10MM DRILLED HOLE AT 12 O'CLOCK POSITION BY UNKNOWN PERSON.



JOINT INVESTIGATION REPORT

INCIDENT NO: 2500137 JIV report S/N: 1030167

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

21. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

S/N	Northing	Easting

SEE ATTACHED
12/10/19

SPILL ALONG 8" ISIMIRI - IMO GATE DELIVERY LINE @UZUAKU

2500137

PT_ID	LAT	LONG
SP	4.8882	7.18307
1	4.88813	7.18315
2	4.88827	7.18246
3	4.88839	7.1821
4	4.88846	7.18185
5	4.88853	7.18175
6	4.8887	7.18158
7	4.88865	7.18154
8	4.88878	7.18142
9	4.88886	7.18135
10	4.88893	7.18125
11	4.88921	7.18107
12	4.88922	7.18109
13	4.88907	7.1812
14	4.88895	7.18128
15	4.88886	7.18142
16	4.88877	7.18151
17	4.88872	7.18159
18	4.88854	7.18176
19	4.88848	7.18187
20	4.88851	7.18188
21	4.88849	7.18195
22	4.88848	7.18204
23	4.88844	7.18205
24	4.88842	7.18212
25	4.88835	7.18233
26	4.88829	7.1826
27	4.88834	7.18261
28	4.88831	7.18264
29	4.88826	7.18271
30	4.88824	7.18282
31	4.88818	7.18298
32	4.88822	7.18301
33	4.88822	7.18306
34	4.8882	7.18315

JOINT INVESTIGATION REPORT

INCIDENT NO: 2500137 JIV report S/N: 1030167

G. INCIDENT INFORMATION:

a. Impacted Area Details

- Total calculated area of impact 0.123343 HA
- Impact within SPDC R.O.W. YES
- Impact outside SPDC R.O.W. YES

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} : 1 BARREL Barrels

Controlled recovery/evacuation from source with no impact to environment:

NIL Barrels

c. Net Estimated Spilled Volume V_{est} (bbls) = 14.93 BARRELS

Estimated Reported Volume** V_{rep} (bbls) = 15 BARRELS

*Notes:

- Volume estimation was done using an excel based tool (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:

NOT APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m^3) \times 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl
Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2019/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).

JOINT INVESTIGATION REPORT

INCIDENT NO: 2500137 JIV report S/N: 1030167

d. General Status of the site

i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/>
ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>


e. Representatives

This report was <u>filled</u> , <u>agreed</u> and <u>signed</u> by the following joint investigation team representatives:	
• Host Community: <input checked="" type="checkbox"/>	
• Department of Petroleum Resources (DPR): <input checked="" type="checkbox"/>	
• National Oil Spill Detection and Response Agency (NOSDRA): <input checked="" type="checkbox"/>	
• State Ministry of Environment (SME): <input checked="" type="checkbox"/>	
• Shell Petroleum Development Company (SPDC): <input checked="" type="checkbox"/>	
• <i>Separate DPR form has been filled out with same findings</i> <input type="checkbox"/>	
	<i>Tick as applicable</i>

JOINT INVESTIGATION REPORT

INCIDENT NO: 2500137 JIV report S/N: 1030167

f. Appendix I: Overview sketch of the site



Version 2019/01

Distribution of copies: White (Assol. Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)