


Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline at Odau-KP9. Picture was taken during Joint Investigation of 9th April 2020.



Close-up: 3" ball valve flange installed at 12 o'clock position on 20" Kolocreek-Rumuekpe Pipeline at Odau-KP9. Picture was taken during Joint Investigation of 9th April 2020.