



Overview: Part of spill impact on 20" Kolocreek – Rumuekpe Pipeline at Odau KM10. Picture was taken during Joint Investigation of 10<sup>th</sup> April 2020.



Close-up: 3" ball valve flange installed at 12 o'clock position on 20" Kolocreek – Rumuekpe Pipeline at Odau KM10. Picture was taken during Joint Investigation of 12<sup>th</sup> April 2020.