



Overview: Part of spill impact on 20” Kolocreek Rumuekpe Pipeline at Odau KP9. Picture was taken during Joint Investigation of 9th April 2020.



Close-up: Failed 3” theft fittings installed at 12 o’clock position on 20” Kolocreek Rumuekpe Pipeline at Odau KP9. Picture was taken during Joint Investigation of 9th April 2020.