




**Overview:** Part of spill impact on 6" Imo River Well 26 Flowline at Igiriukwu. Picture was taken during Joint Investigation of 24<sup>th</sup> April 2020.



**Close-up:** Illegally fabricated 1" clamp at 12 o'clock position on 6" Imo River Well 26 Flowline at Igiriukwu. Picture was taken during Joint Investigation of 24<sup>th</sup> April 2020.