

JOINT INVESTIGATION REPORT

INCIDENT NO: 2629272 JIV report S/N: 0509

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Fountain Incident Number: 2629272 2. Type of incident* OIL SPILL
3. Name of Location 12" IMDB1 - OGALE PIPELINE
ETITIUZO
4. Name of nearest community INUMUOLDLO 5. State: ABIA 6. LGA UKWA WEST
7. Production Facility/Installation OIL PIPELINE
8. Asset Owner/Hub THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED (SPDC)/ PIPELINE

B. INCIDENT INFORMATION:

9. Details of incident

- a. Date Reported: 22ND APRIL 2020
b. Start date/time of Investigation: 23RD APRIL 2020/17:05hrs
c. Investigation End date: 23RD APRIL 2020 Day(s) on site: ONE (1) DAY
d. Description of spill point environment

- | | | |
|---|--|---|
| <input type="checkbox"/> Firm soil | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water | <input type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe surface |
| <input type="checkbox"/> Well Platform (on water) | <input type="checkbox"/> Drill Rig | <input type="checkbox"/> Sand bag(s) |

Additional observations around the spill point:

e. Description of leak point (tick as applicable);

- | | | |
|--|---|--|
| <input type="checkbox"/> Smooth round-edge hole | <input type="checkbox"/> Rough-edge hole | <input type="checkbox"/> Hack saw cut |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Tear (_____) | | |
| <input type="checkbox"/> Others (specify) _____ | | |

f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3rd party damage
 Operational Others (including Mystery spills) _____

*This can be: (a) Oil Spill (b) Drilling fluid/Chemical (c) Siltation (d) Water Leak (e) Fire (f) Non-leaking theft point removal

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

Version 2020/01

JOINT INVESTIGATION REPORT

0509

INCIDENT NO: 2629272 JIV report S/N:

g. Spill Point Coordinates (*Incidents ≤100m apart to be aggregated into one Joint Investigation Report)

h. Measuring unit

AGS 84

Northing: LATITUDE	Easting: LONGITUDE
4.932769	7.184782
23/04/2020	

C. RISK ASSESSMENT

10. Details of Environment

i. Type of environment where spill occurred (select one):

- Land
 Swamp
 Water
 Seasonal swamp
 Shoreline/Waterfront

ii. Type of environment to which oil has spread:

- Land
 Swamp
 Waterbody (specify) _____

iii. Weather condition

- Dry
 Wet
 Windy
 Hot

11. Distance to Sensitive habitat within 100m radius

- Government reserved and designated protected area [,m]
- Drinking water source [,m]
 - Surface water Borehole
- Built up Area [**15** ,m]
 - Residential Area Commercial/Industrial Area
- Farmlands [,m]
- Fish Farm/Pond [,m]
- Fishing net [,m]
- Others (specify) _____ [,m]

12. Containment measures put in place:

- Booms
 Trench
 Dyke
 Pit
 Natural depression
 None
- Others: _____

13. Any pictures or video coverage?

[] [N]

14. Further response/repair initiated as at the time of JIV?

[] [N]

If yes to item 14, give brief description:

SPILL RECOVERY / REPAIRS BY CLAMPING

JOINT INVESTIGATION REPORT

INCIDENT NO: 2629272 JIV report S/N: 0509

15. Was there any disruption to the investigation? [Y] [X]

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y] [X]

Reason(s): **NOT APPLICABLE**

- Delayed Community Access Approval Security Challenges Access constraint due to terrain
 Others (specify)

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
NONE WITHIN AREA OF IMPACT					

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
NONE WITHIN AREA OF IMPACT						

19. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

20. Others (Specify) e.g. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detailed description of the leak point should be contained in the leak report, overview sketch of the site should be added as appendix 1)

A SECTION OF 1 1/2 INCHES LOCALLY FABRICATED CLAMPED INSTALLATION WITH AN ELBOW WORN AT 12 O'CLOCK POSITION BY UNKNOWN PERSON(S) ON 12" IMOR 1 - OGALE PIPELINE AT ETITUZO IN UMUOLO



Version 2020/01

JIV ALONG 12' IMO RIVER TRUNKLINE R.O.W AT ETTIUZO

INCIDENT ID: 2020_2629272

INCIDENT DATE: 22/04/2020

JIV DATE: 23/04/2020

JIV TOTAL AREA ISSUED: 0.073HA

CAUSE OF SPILL: THIRD PARTY INTERFERENCE

BOUNDARY COORDINATES OF IMPACTED AREA (WGS 84)

PT_ID	LONGITUDE	LATITUDE
PL1	7.184793	4.932763
PL2	7.184783	4.932761
PL3	7.184771	4.932748
PL4	7.184730	4.932782
PL5	7.18472	4.932856
PL6	7.184725	4.932952
PL7	7.184727	4.933065
PL8	7.184728	4.933203
PL9	7.184734	4.933323
PL10	7.184739	4.933493
PL11	7.184736	4.933567
PL12	7.184748	4.933682
PL13	7.184753	4.933726
PL14	7.184771	4.933871
PL15	7.184760	4.933897
PL16	7.184760	4.933902
PL17	7.184722	4.933897
PL18	7.184673	4.933892
PL19	7.184644	4.933889
PL20	7.184640	4.933901
PL21	7.184670	4.933901
PL22	7.184720	4.933907
PL23	7.184751	4.933912

PL24	7.184765	4.933904
PL25	7.184780	4.933869
PL26	7.184767	4.933720
PL27	7.184760	4.933683
PL28	7.184785	4.933666
PL29	7.184814	4.933656
PL30	7.184796	4.933624
PL31	7.184791	4.933588
PL32	7.184767	4.933568
PL33	7.184757	4.933491
PL34	7.184747	4.933320
PL35	7.184785	4.933266
PL36	7.184768	4.933206
PL37	7.184802	4.933138
PL38	7.184798	4.933100
PL39	7.184779	4.933005
PL40	7.184846	4.932983
PL41	7.184890	4.932964
PL42	7.184941	4.932981
PL43	7.184958	4.932978
PL44	7.184992	4.932971
PL45	7.184996	4.932928
PL46	7.185038	4.932903
PL47	7.185103	4.932902
PL48	7.185108	4.932870
PL49	7.185051	4.932873
PL50	7.184999	4.932882
PL51	7.184923	4.932892
PL52	7.184903	4.932932
PL53	7.184834	4.932956
PL54	7.184771	4.932940
PL55	7.184778	4.932896
PL56	7.184770	4.932836
PL57	7.184787	4.932789

JOINT INVESTIGATION REPORT

INCIDENT NO: 2629272 JIV report S/N: 0509

G. INCIDENT INFORMATION:

a. Impacted Area Details *

- Total calculated area of impact (Ha) 0.073 Ha
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W YES

* Round off to 2 decimal places if area is $\geq 100 \text{ m}^2$ or to 4 decimal places if area is $< 100 \text{ m}^2$ (e.g. 14.55, 0.0051, 0.0009)
* Express in Hectares (Ha)

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} : 753 BARRELS Barrels

Controlled recovery/evacuation from source with no impact to environment:

8 BARRELS Barrels

c. Net Estimated Spilled Volume V_{net} (bbls)* = 753 BARRELS

Estimated Reported Volume** V_{rep} (bbls) = 8 BARRELS

*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m^3) \times 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl
Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

JOINT INVESTIGATION REPORT

INCIDENT NO: 2629272 JIV report S/N:0509

d. General Status of the site

- | |
|--|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/> |

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:


- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- The Shell Petroleum Development Company [SPDC]:
- *Separate DPR form has been filled out with same findings*
- *Separate NOSDRA form has been filled out with same findings*
- *Separate SME form has been filled out with same findings*

Tick as applicable

JOINT INVESTIGATION REPORT

INCIDENT NO: 2629272 JIV report S/N 509

f. Appendix 1: Overview sketch of the site



Version: 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);
Blue (Host Community)