



Overview: Part of spill impact on 12" ImoRiver2 - Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation 4th August 2020.



Close-up: 3" Welded Neck Flange installed at 12 o'clock position on 12" ImoRiver2 - Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation 4th August 2020.