



Overview: Part of spill impact on 6" Imo River Well 59T Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 8th August 2020.



Close-up: Crude oil theft point installed at 7 o'clock position on 6" Imo River Well 59T Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 8th August 2020.