

JOINT INVESTIGATION REPORT

INCIDENT NO: 2707320 JIV report S/N:

0530

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Fountain Incident Number: 2707320 2. Type of incident* OIL SPILL
3. Name of Location 14th OKORDIA - RUMUEKPE PIPELINE
4. Name of nearest community ULA-IKATA 5. State: RIVERS 6. LGA AKADA - EAST
7. Production Facility/Installation OIL PIPELINE
8. Asset Owner/Hub THE SHELL PETROLEUM DEVELOPMENT COMPANY
OF NIGERIA LIMITED (SPDC)/PIPELINE

B. INCIDENT INFORMATION:

9. Details of incident
a. Date Reported: 12th AUGUST, 2020
b. Start date/time of Investigation: 14th AUGUST, 2020 / 1500HRS
c. Investigation End date: 14th AUGUST, 2020 Day(s) on site: ONE (1) DAY
d. Description of spill point environment

<input type="checkbox"/> Firm soil	<input checked="" type="checkbox"/> Loose soil	<input checked="" type="checkbox"/> Recently excavated area
<input type="checkbox"/> Under water	<input type="checkbox"/> Swampy	<input type="checkbox"/> Exposed pipe surface
<input type="checkbox"/> Well Platform (on water)	<input type="checkbox"/> Drill Rig	<input type="checkbox"/> Sand bag(s)

Additional observations around the spill point:

NOT APPLICABLE

e. Description of leak point (tick as applicable);

- | | | |
|---|---|--|
| <input checked="" type="checkbox"/> Smooth round-edge hole | <input type="checkbox"/> Rough-edge hole | <input type="checkbox"/> Hack saw cut |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Tear () | | |
| <input type="checkbox"/> Others (specify) _____ | | |

f. Incident caused by:

- ☒ Third party interference (Sabotage ☒; crude theft ☐; Line theft ☐; Accidental 3rd party damage ☐
☐ Operational ☐ Others (including Mystery spills) _____

*This can be: (a) Oil Spill (b) Drilling fluid/Chemical (c) Siltation (d) Water Leak (e) Fire (f) Non-leaking theft point removal

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

Version 2020/01

JOINT INVESTIGATION REPORT

INCIDENT NO: 2707320 JIV report S/N:

0530

g. Spill Point Coordinates (*Incidents $\leq 100m$ apart to be aggregated into one Joint Investigation Report)

h. Measuring unit

(WGS 84)

Northings: LATITUDE	Easting: LONGITUDE
5.048980	6.585231

C. RISK ASSESSMENT

10. Details of Environment

i. Type of environment where spill occurred (select one):

☒ Land ☐ Swamp ☐ Water ☒ Seasonal swamp ☐ Shoreline/Waterfront

ii. Type of environment to which oil has spread:

☒ Land ☐ Swamp ☐ Waterbody (specify) _____

iii. Weather condition

☒ Dry ☐ Wet ☐ Windy ☐ Hot

11. Distance to Sensitive habitat within 100m radius

☐ Government reserved and designated protected area [,m]
☐ Drinking water source [,m]
☐ Surface water ☐ Borehole
☐ Built up Area [,m]
☐ Residential Area ☐ Commercial/Industrial Area
☐ Farmlands [,m]
☐ Fish Farm/Pond [,m]
☐ Fishing net [,m]
☐ Others (specify) _____ [,m]

NONE SEEN
WITHIN
VICINITY

12. Containment measures put in place:

☒ Booms ☐ Trench ☒ Dyke ☐ Pit ☐ Natural depression ☐ None

☐ Others: _____

13. Any pictures or video coverage?

☒ [N]

14. Further response/repair initiated as at the time of JIV?

☒ [N]

If yes to item 14, give brief description:

REPAIR AND CRUDE OIL RECOVERY ACTIVITIES ONGOING

JOINT INVESTIGATION REPORT

INCIDENT NO: 2707320 JIV report S/N: 0530

15. Was there any disruption to the investigation?

[Y] [X]

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y] [X]

Reason(s): NOT APPLICABLE

- ☐ Delayed Community Access Approval ☐ Security Challenges ☐ Access constraint due to terrain
☐ Others (specify) _____

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
<u>NONE WITHIN AREA OF IMPACT</u>					

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
<u>NONE WITHIN AREA OF IMPACT</u>						

19. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

20. Others (Specify) e.g. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detailed description of the leak point should be contained in the leak report, overview sketch of the site should be added as appendix 1)

A SECTION OF 14" OKORDIA-RUMUENGE PIPELINE AT ULA-IMTA SHOWING A 12mm DRILLED HOLE AT 1 O'CLOCK POSITION DONE BY UNKNOWN PERSONS.



JOINT INVESTIGATION REPORT

INCIDENT NO: 2707320 JIV report S/N: 0530

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

21. Impacted area boundary Coordinates (If more, Print and attach as Appendix)

S/N	Northing LATITUDE (WGS84)	Easting LONGITUDE (WGS 84)
408	5.050117	6.584072
407	5.050854	6.583303
406	5.051047	6.583207
405	5.051076	6.583344
404	5.050871	6.583529
403	5.050907	6.583589
402	5.051045	6.583624
401	5.050887	6.583763
400	5.050743	6.583692
399	5.050603	6.583861
398	5.050531	6.583856
397	5.050003	6.584387
396	5.049911	6.584414
395	5.049720	6.584591
394	5.049682	6.584673
393	5.049181	6.585097
392	5.048892	6.585375
391	5.048541	6.585736
390	5.048526	6.585687
389	5.048844	6.585287
388	5.048997	6.585065

JOINT INVESTIGATION REPORT

INCIDENT NO: 2707320 JIV report S/N: 0530

G. INCIDENT INFORMATION:

a. Impacted Area Details *

- Total calculated area of impact (Ha) 0.64 HA
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W YES

* Round off to 2 decimal places if area is $\geq 100 \text{ m}^2$ or to 4 decimal places if area is $< 100 \text{ m}^2$ (e.g. 14.55, 0.0051, 0.0009)
* Express in Hectares (Ha)

b. Volume of oil recovered before completion of JIV (V_{recJ}):

Recovered oil V_{recJ} :	<u>NIL</u>	Barrels
-----------------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------


c. Net Estimated Spilled Volume $V_{\text{Est}}(\text{bbls})^* = \underline{271.67 \text{ BARRELS}}$

Estimated Reported Volume** $V_{\text{rep}}(\text{bbls}) = \underline{272 \text{ BARRELS}}$

*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:



Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site;
Conversion of m^3 to barrels is Volume (m^3) $\times 6.29$; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl
Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2020/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);
Blue (Host Community)

JOINT INVESTIGATION REPORT

INCIDENT NO: 2707320 JIV report S/N: 0530

d. General Status of the site

- | |
|--|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/> |

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:


- Host Community: ☒
- Department of Petroleum Resources [DPR]: ☐
- National Oil Spill Detection and Response Agency [NOSDRA]: ☒
- State Ministry of Environment [SME]: ☒
- The Shell Petroleum Development Company [SPDC]: ☒
- Separate DPR form has been filled out with same findings ☐
- Separate NOSDRA form has been filled out with same findings ☒
- Separate SME form has been filled out with same findings ☒

Tick as applicable

JOINT INVESTIGATION REPORT

INCIDENT NO: 2707320 JIV report S/N: 530

f. Appendix 1: Overview sketch of the site



Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);
Blue (Host Community)