

JOINT INVESTIGATION REPORT

INCIDENT NO: 2718876 JIV report S/N: 0690

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Fountain Incident Number: 2718876 2. Type of incident* OIL SPILL
3. Name of Location 28" BOMU - BONNY PIPELINE
4. Name of nearest community OWOKIRI 5. State: RIVERS 6. LGA ANDONI
7. Production Facility/Installation OIL PIPELINE
8. Asset Owner/Hub THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LTD (SPDC) / PIPELINE

B. INCIDENT INFORMATION:

9. Details of incident

- a. Date Reported: 28TH AUGUST 2020
b. Start date/time of Investigation: 30TH AUGUST 2020/1320HRS
c. Investigation End date: 30TH AUGUST 2020 Day(s) on site: ONE (1) DAY
d. Description of spill point environment

- | | | |
|---|--|--|
| <input type="checkbox"/> Firm soil | <input type="checkbox"/> Loose soil | <input type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water | <input checked="" type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe surface |
| <input type="checkbox"/> Well Platform (on water) | <input type="checkbox"/> Drill Rig | <input type="checkbox"/> Sand bag(s) |

Additional observations around the spill point:

NOT APPLICABLE

e. Description of leak point (tick as applicable);

- | | | |
|--|---|--|
| <input type="checkbox"/> Smooth round-edge hole | <input type="checkbox"/> Rough-edge hole | <input type="checkbox"/> Hack saw cut |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Tear (_____) | | |
| <input type="checkbox"/> Others (specify) _____ | | |

f. Incident caused by:

- ☒ Third party interference (Sabotage ☐; crude theft ☒; Line theft ☐; Accidental 3rd party damage ☐
☐ Operational ☐ Others (including Mystery spills) _____

*This can be: (a) Oil Spill (b) Drilling fluid/Chemical (c) Siltation (d) Water Leak (e) Fire (f) Non-leaking theft point removal

Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

JOINT INVESTIGATION REPORT

0690

INCIDENT NO: 2718876 JIV report S/N:

g. Spill Point Coordinates (*Incidents $\leq 100m$ apart to be aggregated into one Joint Investigation Report)

h. Measuring unit

WGS 84

Northings:	Easting:
LATITUDE	LONGITUDE
4.54220	7.24616

C. RISK ASSESSMENT

10. Details of Environment

i. Type of environment where spill occurred (select one):

☐ Land

☒ Swamp

☐ Water

☐ Seasonal swamp

☐ Shoreline/Waterfront

ii. Type of environment to which oil has spread:

☐ Land

☒ Swamp

☐ Waterbody (specify) _____

iii. Weather condition

☒ Dry

☐ Wet

☐ Windy

☐ Hot

11. Distance to Sensitive habitat within 100m radius

☐ Government reserved and designated protected area

☐ Drinking water source

☐ Surface water

☐ Borehole

☐ Built up Area

☐ Residential Area

☐ Commercial/Industrial Area

☐ Farmlands

☐ Fish Farm/Pond

☐ Fishing net

☐ Others (specify) _____

[,m]
[,m]
[,m]
[,m]
[,m]
[,m]
[,m]

NONE SEEN
WITHIN
VICINITY

12. Containment measures put in place:

☐ Booms

☐ Trench

☒ Dyke

☐ Pit

☐ Natural depression

☐ None

☐ Others: _____

13. Any pictures or video coverage?

☒ [N]

14. Further response/repair initiated as at the time of JIV?

☒ [N]

If yes to item 14, give brief description:

BLIND FLANGING

JOINT INVESTIGATION REPORT

INCIDENT NO: 2718876 JIV report S/N: 0690

15. Was there any disruption to the investigation?

[Y] ☒ [N]

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed?

[Y] ☒ [N]

Reason(s): NOT APPLICABLE

☐ Delayed Community Access Approval

☐ Security Challenges

☐ Access constraint due to terrain

☐ Others (specify)

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	<u>NONE WITHIN AREA OF IMPACT</u>				

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	<u>NONE WITHIN AREA OF IMPACT</u>					

19. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	<u>NONE WITHIN AREA OF IMPACT</u>			

20. Others (Specify) e.g. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	<u>NONE WITHIN AREA OF IMPACT</u>			

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detailed description of the leak point should be contained in the leak report, overview sketch of the site should be added as appendix 1)

BOMU - BONNY PIPELINE AT OWOKIRI SHOWING 6" CRUDE OIL THEFT VALVE, INSTALLED AT 12 O'CLOCK POSITION BY UNKNOWN PERSON(S)



JOINT INVESTIGATION REPORT

INCIDENT NO: 2718876

JIV report S/N: 0690

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

21. Impacted area boundary Coordinates (If more, Print and attach as Appendix)

WG 84

S/N	Northing LATITUDE	Easting LONGITUDE
1	4.54211	7.24609
2	4.54226	7.24613
3	4.54223	7.24620
4	4.54214	7.24620
5	4.54230	7.24625
6	4.54231	7.24629
7	4.54212	7.24623
8	4.54196	7.24627
9	4.54186	7.24620
10	4.54173	7.24615
11	4.54174	7.24610
12	4.54187	7.24617
13	4.54197	7.24626
14	4.54205	7.24623
15	4.54212	7.24617
16	4.54211	7.24614

JOINT INVESTIGATION REPORT

INCIDENT NO: 2718876 JIV report S/N: 0690

G. INCIDENT INFORMATION:

a. Impacted Area Details *

- Total calculated area of impact (Ha) 0.04 Ha
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W YES

* Round off to 2 decimal places if area is $\geq 100 \text{ m}^2$ or to 4 decimal places if area is $< 100 \text{ m}^2$ (e.g. 14.55, 0.0051, 0.0009)
* Express in Hectares (Ha)

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} :	<u>NIL</u>	Barrels
----------------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

c. Net Estimated Spilled Volume $V_{\text{Est}}(\text{bbls})^* =$

1.88 BARRELS

Estimated Reported Volume** $V_{\text{rep}}(\text{bbls}) =$

2 BARRELS

*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is $\text{Volume (m}^3) \times 6.29$; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl
Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2020/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

JOINT INVESTIGATION REPORT

INCIDENT NO: 271 8 8 7 6 JIV report S/N:0690

d. General Status of the site

- | | |
|---|-------------------------------------|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out | <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works | <input checked="" type="checkbox"/> |

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community: ☒
- Department of Petroleum Resources [DPR]: ☐
- National Oil Spill Detection and Response Agency [NOSDRA]: ☒
- State Ministry of Environment [SME]: ☒
- The Shell Petroleum Development Company [SPDC]: ☒
- *Separate DPR form has been filled out with same findings* ☐
- *Separate NOSDRA form has been filled out with same findings* ☒
- *Separate SME form has been filled out with same findings* ☒

Tick as applicable

JOINT INVESTIGATION REPORT

INCIDENT NO: 2718876 JIV report S/N: 690

f. Appendix 1: Overview sketch of the site

