



Overview: Part of spill impact on 4" ImoRiverWell 60T Flowline at Odagwa. Picture was taken during Joint Investigation on 7th December 2020.



Close-up: Crude oil theft point installed at 12 o'clock position on 4" ImoRiverWell 60T Flowline at Odagwa. Picture was taken during Joint Investigation on 7th December 2020.