



**Overview:** Part of spill impact on 14" Okordia Rumuekpe Pipeine at Edeoha.  
Picture was taken during Joint Investigation on 22nd Dec 2020.



**Close-up:** 2" valve installed at 12 o'clock position connected to a 2" galvanized pipe on 14" Okordia Rumuekpe Pipeine at Edeoha. Picture was taken during Joint Investigation on 22nd Dec 2020.