




Overview: Part of spill impact on 20'' Kolocreek Rumuekpe Pipeine at Owerewere. Picture was taken during Joint Investigation on 23rd Dec 2020.



Close-up: 2'' valve installed at 12 o'clock position connected to a 2'' galvanized pipe on 20'' Kolocreek Rumuekpe Pipeine at Owerewere. Picture was taken during Joint Investigation on 23rd Dec 2020.