



Overview: Part of spill impact on 20" Kolocreek – rumuekpe Pipeline at Owerewere . Picture was taken during Joint Investigation 5th July 2020.



Close-up: Failed 3" Ball valve fittings installed at 12 o'clock position on 20" Kolocreek – rumuekpe Pipeline at Owerewere . Picture was taken during Joint Investigation 5th July 2020.