



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Idu-Ekpeye .  
Picture was taken during Joint Investigation 18th July 2020.



Close-up: Failed 2inch ball valve fittings installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Idu-Ekpeye . Picture was taken during Joint Investigation 18th July 2020.