



**Overview:** Part of spill impact on 4" Imo River Well 32L Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 30<sup>th</sup> July 2020.



**Close-up:** Hack Saw Cut on 4" Imo River Well 32L Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 30<sup>th</sup> July 2020.